

WAC 296-301-210 Handling caustic soda and caustic potash. Means must be provided for handling and emptying caustic soda and caustic potash containers to prevent workers from coming in contact with the caustic (see WAC 296-301-220).

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 17-18-075, § 296-301-210, filed 9/5/17, effective 10/6/17; Order 74-19, § 296-301-210, filed 5/6/74.]