

**WAC 296-303-030 Moving parts.** (1) Machine guarding (other than point of operation). Moving parts of machines, such as gears, sprockets, belts, pulleys, and shafts, must be guarded in accordance with the requirements of chapter 296-806 WAC, Machine safety.

(2) Prime-mover guarding. Moving parts of prime movers such as fly-wheels, cranks and connecting rods, tail rods or extension piston rods, and governor balls, must be guarded in accordance with the requirements of chapter 296-806 WAC, Machine safety.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, and 49.17.060. WSR 17-18-075, § 296-303-030, filed 9/5/17, effective 10/6/17; WSR 04-14-028, § 296-303-030, filed 6/29/04, effective 1/1/05; Order 74-18, § 296-303-030, filed 5/6/74.]