

**WAC 296-806-20016 Prevent overspeed conditions.** You must operate tools and equipment within their rated speed.

**Note:** Actions that could cause an overspeed condition include:  
1. Installing a more powerful motor.  
2. Changing or increasing the power source.  
3. Changing attachment size or type, such as a blade or wheel.  
The attachment speed (rpm) and motor speed (rpm) should match.

[Statutory Authority: RCW 49.17.010, 49.17.040, 49.17.050, 49.17.060. WSR 15-24-102, § 296-806-20016, filed 12/1/15, effective 1/5/16; WSR 04-14-028, § 296-806-20016, filed 6/29/04, effective 1/1/05.]