- WAC 296-150C-1050 Drilling or notching of wood joist structural members. (1) Notches on the ends of joists must not exceed one-fourth the joist depth, unless substantiated by engineering design or approved tests.
- (2) Holes bored in joists must not be within two inches of the top or bottom of the joist, and the diameter of any such hole must not exceed one-third of the depth of the joist.(3) Notches in the top or bottom of the joists must not exceed
- (3) Notches in the top or bottom of the joists must not exceed one-sixth the depth and must not be located in the middle third of the span.
- (4) Joists in transverse floor framing systems, which do not have perimeter blocking, must not be drilled or notched, unless substantiated by engineering design or approved tests.

[Statutory Authority: RCW 43.22.340, [43.22.]355, [43.22.]360, [43.22.]432, [43.22.]440 and [43.22.]480. WSR 96-21-146, § 296-150C-1050, filed 10/23/96, effective 11/25/96.]